


**Material**  
High tension brass.


## ORDERING METHOD

**SRF - 4060 B**  
Parts No.

● Use this item in combination with the CWR (Positive Wear Plate).



## ● Application



Parts No.

**SRF-4060B**

**CAD**