


Material
OILES#500F (Gray Iron Casting with graphite plugs.)

ORDERING METHOD

FUP - 28200
Parts No.

Ex.:T28mm×L200mm

● The operation direction is the length (L) direction.



Material
OILES#500SP (High tension brass with graphite plugs.)



ORDERING METHOD

SUP - 28200
Parts No.


Ex.:T28mm×L200mm

● The operation direction is the length (L) direction.


L=160




L=200, 240



L=300, 340



● Application



Parts No.		T	L	W	W1	l1	l2	W2	φd	Holes
FUP-25160	SUP-25160		160		25		110			2
FUP-25200	SUP-25200	25	200	70		25	75	50	18	
FUP-25240	SUP-25240		240			30	90			
FUP-28200	SUP-28200		200		30	25	75			3
FUP-28240	SUP-28240		240			30	90			
FUP-28300	SUP-28300	28	300	85			30	80	60	22
FUP-28350	SUP-28350		350				40	90		

CAD